

DEPARTMENT OF ENVIRONMENTAL QUALITY

ENVIRONMENTAL RESPONSE DIVISION

ACTIVITY REPORT

EPA Region 5 Records Ctr.



208042

Activity

☒ PEAS# 97-245
☐ Clean-up Activities
☐ Site Inspection
☐ Contractor Oversight
☐ Telephone Conversation

☐ RI/FS
☐ Samples Taken
☒ Photos Taken
☐ Other

Program

☒ Part 201
☐ Bond
☐ Part 31
☐ Part 115
☐ Part 111

Date: June 25, 1997

Facility/Site Name

Durako Paint & Color Corp.

County

Wayne

Telephone

Address

6315 E. Seven Mile Road

City/Township

Detroit

Staff/Participants: Ray Spaulding, MDEQ-ERD & Rich Berak, MDEQ-ERD

REMARKS: We arrived on site at approximately 10:00 AM. We found approximately (350) 55-gallon drums full of paint related materials on a storage lot east of Filer Street. In addition to the full drums, there at least 300 empty drums and several tote tanks along with several mixing tanks. The lot is unsecured and several of the drums are open or in a state of deteriorated condition.

There are approximately 40 drums located outside the east end the building. There are 332 drums inside the east end of the building. 64 drums outside the main storage room and approximately 2000 drums inside the main storage area (see diagram). The drums inside the building are stacked neatly on pallets and are in fairly good condition.

There is a large amount of pallet materials on site as well as a few gasoline containers. The back of the building is unsecured and open the alley. There are five underground storage tanks listed on the database as removed for Durako. The status of the tanks are uncertain at this time as the initial abatement report was not in the file.

Off site at approximately 11:00 AM.

Recommended Actions: Refer the sight to Jason El-Zein, USEPA for evaluation.

cc: Mary Vanderlaan, ERD

Signature

Ray Spaulding

Date

6/25/97

Page

1

of

3